

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

920
NNW
> 1
1.230 mi.
6494 ft.

VAULT VS5445
BENSON AVE & 25TH AVE
BROOKLYN, NY

NY Spills S106009128
N/A

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name: VAULT VS5445
Address: BENSON AVE & 25TH AVE
City,State,Zip: BROOKLYN, NY

Spill Number/Closed Date: 0208244 / 2003-02-20

Facility ID: 0208244

Facility Type: ER

DER Facility ID: 175033

Site ID: 211153

DEC Region: 2

Spill Cause: Equipment Failure

Spill Class: C3

SWIS: 2401

Spill Date: 2002-11-08

Investigator: JHOCONNE

Referred To: Not reported

Reported to Dept: 2002-11-08

CID: 365

Water Affected: Not reported

Spill Source: Commercial/Industrial

Spill Notifier: Responsible Party

Cleanup Ceased: Not reported

Cleanup Meets Std: False

Last Inspection: Not reported

Recommended Penalty: False

UST Trust: False

Remediation Phase: 0

Date Entered In Computer: 2002-11-08

Spill Record Last Update: 2003-02-20

Spiller Name: Not reported

Spiller Company: CON EDISON

Spiller Address: 4 IRVING PLACE

Spiller Company: 001

Contact Name: Not reported

DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was
O'CONNELL e2mis no. 145-964: 08-NOV-2002 11:15 HRS. WHILE ON LOCATION
FOR INSPECTION WORK ON VS-5445 FEEDER 7B45 FOUND: APPROX. 40 GAL'S OF
UNKNOWN OIL ON APPROX. 200 GAL'S OF WATER. (POSSIBLE BOTTOM
LEAKER). SPILL IS CONTAINED. NO SEWERS OR WATER WAYS APPEAR TO BE
AFFECTED. THERE IS NOT NOW NOR WAS THERE PRIOR FIRE INVOLVEMENT
.THERE IS NOT NOW NOR WAS THERE PRIOR SMOKE INVOLVEMENT. NO KNOWN
SUMP OR PUMP. NO KNOWN SEWER CONNECTION PRESENT. NO PRIVATE PROPERTY
AFFECTED. NO KNOWN SUBSTANTIAL CRACKS IN STRUCTURE. ENVIR. TAG
PLACED. LIQ. SAMPLE TO BE TAKEN & MARKED PRIORITY E . EQUIPMENT
HISTORY: HISTORICAL PCB 34 PPM.2-20-96. SERIAL # NBV 600145, MFR. WE.
YR. OF MFR. 01/01/1971. UNABLE TO PRESSURE TEST DUE TO FEEDER BEING
ENERGIZED. UNIT IS WELL BELOW MIN. CLEANUP BEING DONE AS 50-499. UNIT
CAPACITY 307 GAL'S - FLUID REMAINING - APPROX. 267 GAL'S = DIFFERENCE
OF 40 GAL'S. Update 1430hrs J. Gaglio env. mgr reports ERT D. Kinberg
on location and DEP Roberto Diaz arrived on location @ 1410hrs. Netw
is pressure testing unit at this time. UPDATE***** 15:15HRS G.
PALADINO REPORTS, PRESSURE TESTED TRANSFORMER AND FAILED. DIPPED
TRANSFORMER 9 BELOW TOP OF TRANSFORMER. TOOK PCB SAMPLE FROM
TRANSFORMER AND NOW WAITING FOR SAMPLE TO BE PICKED UP AT LOCATION.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UPDATE 11/8/02 1850 TANKER REMOVED 307 GALS OF OIL FROM TRANSF AND
258 GALS OF LIQUID FROM VAULT. SUMP FOUND CEMENTED. Update - 2020 hrs
11/8/02 C. Lugo, env. ops reports initial clean up completed.
Structure and unit has been drained and tag remains in place pending
results and removal of transformer. LAB RESULT RECEIVED 11/8/02 -
2125. 02-10535. 20 PPM. UPDATE 11/13/02 13:45 HRS. TRANSFORMER
REMOVED BY EQUIPMENT GROUP, THEN HE DOUBLE-WASHED STRUCTURE WITH
SLIX, FOUND SUMP ALREADY CEMENTED AND REMOVED ENV. STOP TAG. CLEANUP
IS 100 COMPLETE AT THIS TIME."
Remarks: "starting clean up as 50-499 ppm pcb's - samples have been taken -
ref #145964"

All Materials:

Site ID: 211153
Operable Unit ID: 859752
Operable Unit: 01
Material ID: 515246
Material Code: 0020A
Material Name: transformer oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 40.00
Units: G
Recovered: .00
Oxygenate: Not reported